
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/30/2009
Test to be performed: Ground Condition: Smoke Dyed Water X Dry ✓ Damp Wet		Supervisor: <u>JAW</u>
Manhole_ID: S01WW_013MH	Test ID: <u>D1032-025006</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01WW_001MH
0			Water Level	
52.59999847			Dye Test Not Visible	
52.59999847			Abandoned Survey	DYE TEST IS COMPLETE